FEB 1952 51-4AA

CENTRAL INTELLIGENCE AGENCY

CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY SECURITY INFORMATION

50X1-HUM

INFORMATION REPORT

CD NO.

COUNTRY

East Germany

DATE DISTR. 17 October 1952

SUBJECT

DATE OF

Soviet Armored Vehicle Repair Shop

NO. OF PAGES

NO. OF ENCLS.

PLACE ACQUIRED

SUPPLEMENT TO REPORT NO.

50X1-HUM

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES, WITHIN THE MEANING OF TITLE 18, SECTIONS 793 AND 794, OF THE U.S. CODE, AS AMENDED. ITS TRANSISSION OR REVELATION OF ITS CONTENTS TO OR RECEIPT BY AN UNAUTHORIZED PERSON IS PROMIBITED BY LAW. THE REPRODUCTION OF THIS FORM IS PROHIBITED.

THIS IS UNEVALUATED INFORMATION

50X1-HUM

- 1. Repairs on the following armored vehicles had been completed at the armored vehicle repair shop at Schoenebeck during May: 4 JSU 122's, 4 SU loo's, 14 T 34/85's. Although completed, the vehicles remained at the workshops.
- 2. Ten SU loo's 24 T 34/85 tanks and 4 T 34 Bridge (sic) tanks were still undergoing repairs during May.
- 3. The installation of an ammunition bunker on the site of the former antiaircraft position is the only change which has recently taken place at the
 workshops. The bunker is very closely guarded by sentries accompanied by
 dogs, and instructions have been given to shoot without challenge at anyone
 approaching the bunker within five meters.
- 4. Command of twhe area in the vicinity of Schoenebeck has been concentrated under one military command. Independent kommandaturas had previously existed in Schoenebeck, Calbe, Wanzleben and Wolmirsleben.
- 5. The "Lager-Silos" in Schoenebeck-Frone have recently been occupied by approximately 4,000 infantry troops.
- 6. On 20 April, load tests were carried out on a newly constructed bridge over the Elbe at Schoenebeck. For these tests four JSU 122's were used. The tests took form of sending one vehicle across, then two in close formation, then three, etc. It was decided that three vehicles was the maximum the bridge could support with safety, although four had been sent across.
- 7. It was recently noted that a JS 3 had four ammunition boxes fitted at section with rope handles. The ammunition boxes were approximately 340 mm. x 985 mm. and are believed to have contained live ammunition consisting of two tiers of ammunition to each box.

50X1-HUM

CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY

STATE		NAVY		NSRB	DISTRIBUTION	
	x	AIR	x	FBI		